








Case Study: Garage Access Ramp



Interclamp®
The right connection



Interclamps were used to solve this customer's problem when he removed soil from around his garage that then prevented him reaching the storage area above. He could see the benefit of using Interclamps to construct this tubular ramp with handrails instead of having a ramp welded or built out of blocks. The 144 fittings have been used to secure the framework to the side of the building, an ideal solution and another happy customer.

